


STROBE LIGHT SG16



To install strobe light:

Using grommet supplied, drill 3/8" hole in bottom of control box, install grommet, then feed strobe cable through grommet.
Fit 2 way plug to strobe wire with RED on left and BLACK on right as shown.
Plug into STROBE terminals as shown.

Strobe light will flash 5 seconds before gate closes and continue flashing until closed.
Strobe light will flash for 2 seconds when gate is locked, and for 2 seconds if visitor/remote button is pressed when gate is locked.

SO_ELE68